

Chemical Incident Investigation

Millennium Inorganic Chemicals (MIC)

Stallingborough UK, 2010

May 2019

Contributors

Brian Fotheringham

Stephen Hargreaves

Jonathan Buston

Stephen Graham






Unit
600

Coastal
Path


Titanium Dioxide- The Chloride Process




Plant Schematic



Plant Schematic



Plant Schematic



Unit 600: Scene of a Violent Reaction



D650



D650



Two of the Investigation Challenges

Only residual amounts of TiCl_4 are expected to be in the gas stream when it enters D650 and it was evident early on in the investigation that an unknown amount of liquid TiCl_4 had entered the vessel resulting in a violent reaction and causing catastrophic failure

- 1st Challenge was to find out how the liquid TiCl_4 had passed over from the condensation train and why it had failed at that particular time
- 2nd Challenge was to understand if the white cloud which left site posed a risk to members of the public

So why did Vessel D650 fail...?

“Unexpectedly large volume of TiCl_4 reacted at once”


The Reaction:




Second example of
violent reaction between
 TiCl_4 and water

21st March 2011

Pressure Increases



- Pressure rise 0-1 bar about 400ms
- Final Pressure 3.13 bar
- 1.3 bar could be from hydrochloric acid




So why did Vessel D650 fail...?

*“Unexpectedly large volume of TiCl_4 reacted
at once”*


Where did the TiCl_4 come from?

Unit 200 Condensation Train



CONDITIONS WHEN WARM UP IS
STOPPED PREMATURELY ON
4 MARCH AT 00:50


New upper operating limit of
-5° is reached and warm up is
stopped prematurely



CONDITIONS DURING THE DAY SHIFT 4 MARCH

Water and brine off to enable repair

Significant quantities of $TiCl_4$ enter D650.
Unknown quantities of water are added to thin down the contents



So why did Vessel D650 fail...?

“Unexpectedly large volume of TiCl_4 reacted at once”

How did the TiCl_4 arrive and cause the vessel to fail?


Two options

D650



Gas flow from Unit
200 enters S650
where high speed
mixing takes place

Gas flow exits to
D651



Base of Unit 650; Pumps



Pump Bolts



Foam formation: 500ml cylinder


Titanium tetrachloride
added down side of
cylinder

500ml measuring cylinder
Internal diameter 48mm

Thermocouple group,
2cm apart vertically,
wrapped in PTFE tape.
Bottom in liquid, next
one above liquid

37% Hydrochloric acid,
preheated to ca 35°C

Cross shaped
magnetic stirrer bar




Example of crust formation

Addition of TiCl_4 to HCl


13th December 2010

Foam formation: 500ml cylinder

MIC Expt Book 1 p 17



Foam formation: 500ml cylinder





Subsequent sequence of events

- Warm-up / Start-up continued on 5th March
- Less than optimal conditions in **D650**
 - Blockages / Twaddle Readings
- Additional water added to dilute the scrubbing mixture
- Pump stopped to clear sampling ports
- Pump turned back on

Subsequent sequence of events

- Fume seen from pump
- Decision to switch over to auxiliary pump

VESSEL RUPTURED

- Rescue of injured
- COMAH Emergency plan initiated

Subsequent consequences

- Harm to people
- Dense white cloud left site, closing Humber to traffic
- Company submitted guilty pleas (to all three charges) in May 2016

Generic Lessons



Questions?

