

# How Process Safety Can Apply Outside the Process Industries - Taming the Wild River Rapids

Trish Kerin, IChemE Safety Centre, Level 7, 455 Bourke St, Melbourne, Victoria, Australia, tkerin@icheme.org

On the 25th October 2016 the Thunder River Rapids ride at Dreamworld on Australia's

Gold Coast suffered a pump failure, resulting in the tragic deaths of four riders. This incident was investigated by the police and later a coronial inquest to determine how a tragedy like this could occur. As a process safety professional, it was interesting to follow the coronial inquest findings and then think about how process safety management may have helped to prevent this incident. If a process safety event can be defined as a high consequence or potential consequence low likelihood loss of control event (Kerin, 2017), this incident had all the hallmarks. Therefore, it is possible to apply the ISC framework (ISC, 2014) for process safety to identify where the system failed and understand how it could be averted in future. This paper will explore various elements of the incident and how process safety management techniques may have helped, including that the ride had been modified to be different from all other similar rides, that the staff did not know how to stop the ride in an emergency and that all means to stop the ride required manual detection and intervention, with no alarms or shut down systems installed.

Keywords: lessons learned, process safety, design, maintenance

## The Incident

The Thunder River Rapids ride at Dreamworld in Queensland, Australia, was a water ride, simulating white water rafting. Up to six riders sit in a circular raft, which flows along a turbulent river, including travelling up a conveyor to ride down a waterfall. The water flow is driven by pumps and made turbulent by the installation of underwater obstacles. It was in full operation on 25th October 2016, when the pump managing the water flow tripped out. This resulted in the water level on the ride dropping. This drop in water level caused a raft to become stuck on the rails at the conveyor leading to the disembarkation platform. This raft remained stationary for some 57 seconds while the ride continued to run before it was impacted by the next raft in the sequence. This following raft contained 6 passengers, four adults and two children. When this raft struck the stationary one, it flipped over, killing the four adult passengers. The two children managed to escape the raft (Sibson, 2018). This incident is currently under a Coronal Inquest. As such this paper is written from several media outlets that have been reporting the proceedings and based on the evidence reported, not the findings of the Coroner. The Coronal Report is due to be published in mid 2019.

## History of the Ride

The Thunder River Rapids ride was completed in 1986 and was likely an in-house design and construction. Sometime after construction, the ride was modified to remove some of the timber slats that form the base of the conveyor. (Ludlow, 2016) Two in every three slats were removed, though is unclear why this was done. This did create significant gaps in the base of the conveyor belt. The ride was also refurbished some months prior to the incident. (AAP vid 11, 2018).

Over the history of the ride there had been several incidents that had occurred with the rafts and the pumps. This is not unusual, in that pumps can trip out from time to time, however there had been an incident in 2001 where the pump had tripped, and a raft became stuck (Wolfe, 2018). This was then struck by a second raft, which flipped over. In this incident there were no passengers in the raft, and therefore no injuries. The investigation found that the ride operator had failed to adequately monitor the ride and he was dismissed. Details of this incident were not shared broadly and the operators and maintainers of the ride in 2017 had no knowledge of it. At the time an email was written by a park engineer discussing the incident and stated, "I shudder when I think if there had been guests on the ride" (Sibson, 2018). This demonstrates that someone at some time recognized the significance of this incident, but it was then lost in history.

## Technical and Organizational Causes of the Incident

There is one key immediate cause of this incident, however there are many different and wide-ranging causal factors. The immediate cause has been determined to be the tripping of the water pump, which in turn allowed the water level to drop, causing the first raft to become stuck. This provided the obstacle that the second raft, with six passengers, struck, causing it to then flip over. But let us examine the broader aspects of this incident, from the pump reliability to the safety systems and organizational capability. The ISC framework (ISC, 2014) provides a useful template to examine the causes. This framework is represented by Figure 1. Fundamentally leadership underpins all aspects of process safety. There are six functional elements that must be robust in an organization to manage major hazard safety. These are; knowledge & competence; engineering & design; systems & procedures; assurance; human factors and culture. In this incident there were clear failures in each of these elements.

## Knowledge & Competence

The training of the ride operators took only 90 minutes and was unstructured with no evidence of competence consistently recorded (Sibson 2018). There was a procedure manual however it was thought to be confusing (Sibson 2018). The operator running the ride on 25th October 2016 had been trained for 90 minutes that morning, as it was her first day running the Thunder River Rapids. The junior operator stated that the trainer "showed me the front page of the manual and just flipped through it. I had to go through it myself. She said just sign off on it when you are happy." (AAP vid 5, 2018) The trainer stated that she

sometimes had to “invent” training techniques because of the complexity of the control panel (Sibson, 2018). There was no clear guidance on how and when to use the emergency stop for the ride. The new operator testified that she was told “don’t worry about it, you don’t need to use it” about the emergency stop button. This is disputed by the person who delivered the training. The new operator believed it was the role of the senior operator to shut the ride down. It should be noted that the emergency stop would shut down the moving equipment with in two seconds, where the normal shutdown took around eight seconds. The ride operator that day stated that she “would have waited for the senior operator to tell her to hit the e stop” (Sibson, 2018). The senior operator that day was “surprised” to learn there was an emergency stop that would have shut the ride down within two seconds (Sibson, 2018).



Figure 1. ISC Framework for Process Safety

**Engineering & Design**

Intamin Amusement Rides designed and built the first river rapids rides in the world, and following this tragedy released a statement stating that the ride was “neither built by Intamin nor supplied by Intamin”. The ride at Dreamworld was a custom build, and this was said to be common for rides built in the 1980’s in the Gold Coast (Ludlow, 2016).

The Timber Slats

A few years after the ride was opened, a modification was made to the timber slats in the conveyor system (Ludlow, 2016). The slats appear to serve at least two safety purposes. The first was to provide a solid platform for a passenger if they fell from the raft, essentially isolating them for the moving machinery and providing a platform to stand on (AAP, 2018). The second was so that the rafts did not get caught in gaps and become stuck or indeed flip over. The Thunder River Rapids ride had two of every three slats removed. This provided large gaps between the remaining slats. There does not appear to be a theme park anywhere else that has made this change. There also appears to be no evidence as to why the change was made, nor was there a considered Management of Change review undertaken. The safety regulator did not approve the modification and believed it added in additional hazards (Ludlow, 2016) (AAP, 2018). In this incident, the raft became lodged in the gap, and as the conveyor continued to move forward, the raft was driven up vertically. When the passengers then fell from the raft, there was no solid base and they landed in the mechanism of the conveyor. There had also been conveyor framework modifications made to the ride in early 2016 to stop rafts flipping over (Huxley, 2018). No information on why of how this was done was available.



Figure 2. Aerial view of Thunder River Rapids showing the large gaps in the timber slat conveyor after the incident (Sibson, 2018).



Figure 3. Aerial view of Infinity Falls, Orlando, showing close spacing of the boards on the conveyor (Intamin, 2018).

### The Pump

The water pumps had failed three times in the days leading up to the incident, and then twice on 25th October 2016, before the final failure that led to the tragedy (AAP vid 8, 2018). The pump's purpose was to keep the water flowing through the ride to keep the rafts moving. If the pumps stopped the water not only stopped flowing, it also drained back, and the water level dropped such that rafts could become stuck on the underwater obstacles that produced the rapids (Sibson, 2018). The reason for the pumps tripping out was not determined, the protocol seemed to be to just reset them to get the ride operating again (Sibson, 2018). There also is some confusion as to whether an alarm was sounded when the pumps tripped out, with an old procedure having the comment about an alarm crossed out (Jackson, 2018). At the time of the incident the pumps were approximately 10 years old, and the manufacturer stated that they had a life expectancy of about a decade. There did not appear to be any plans to replace the pumps, however there was a maintenance request into the pump supplier in the week prior, but this visit did not eventuate (AAP vid 10, 2018).

### Low Water

Low water in the ride was a critical hazard, as the rafts could become stuck or indeed flip. There had been previous incidents where low water level hazard led to rafts flipping, notably in 2001. There was no low water level switch that would shut down the ride if the water level became too low (Sibson, 2018). The only indication the operators had was to notice the water stain level on the wall of the ride canal to determine if the water was too low (Sibson, 2018). When the water level dropped on 25th October, one empty raft became stuck on the rails near the base of the conveyor. As the second raft containing four adults and two children engaged with the conveyor it was then driven into the stuck raft. A safety review conducted after the event stated that the primary cause was a lack of a safety rated water level detection system. It was believed that such a device could have been fitted for as little as AUD 3,000. The ride had been refurbished some seven months prior to the incident, but a device was not fitted. The nearby log ride at the park had such a safety device fitted (AAP vid 10, 2018).

### Emergency Stop

Around two years prior to the incident an external safety report was written suggesting the emergency stop system should be simplified, however this was rejected by the company as the emergency system in place was seen to be an "acceptable risk". The stopping procedure for the ride contained several individual steps. There was a single button which would stop all components of the ride, however this was located at the unloading area and not the control panel where the operators worked. (Wolfe, 2018)

There was a great amount of confusion regarding the emergency stop button and what it did. The senior operator stated that they were "surprised" to learn there was an emergency stop that would stop all components and the junior operator on her first day was unsure what the button did (Sibson, 2018). She stated she was told not worry about the button because she did not need to use it and testified, she "would have waited for my senior operation to tell me to press it". She also did not know the button would stop the conveyor from moving. (Sibson, 2018) The maintenance workers who performed the daily checks on the ride also stated they did not know what the emergency stop button did as they never tested it (Jackson, 2018).

### Maintenance

Seven months prior to the incident a directive to cut all repairs and maintenance spending was ordered by the owners. At the time of the incident the facility was approximately AUD125,000 over maintenance budget for the year to date. Capital expenditure could continue to be spent during this time (Sibson, 2018). One maintainer stated that he performed comprehensive daily, monthly and annual checks on the ride, which include consumable replacements such as nuts and bolts (Sibson, 2018). When the regulator inspected the ride after the incident, he noted it was in "generally poor condition" with excessive corrosion and rust on the electrical cables (Wolfe, 2018).

The maintenance planner noted that if spending could be deferred it would be. He also noted that the ride was shut annually for review, but on the nine occasions he witnessed a shutdown, he never saw an engineer inspect the ride nor were any risk assessment carried out (AAP vid 20, 2018).

### Seatbelts

The Thunder River Rapids rafts had seat belts fitted for the safety of the riders. It should be noted that in May 2017, some seven months after the Dreamworld incident, that an 11 year old girl died on a similar ride, Splash Canyon, at Drayton Manor in the United Kingdom. The Splash Canyon ride rafts had no seatbelts installed at all, and as the child stood to swap seats with a fellow rider she fell overboard and struck her head. She died days later in hospital. This was not the first time a rider had fallen from the Splash Canyon ride (The Sun, 2017). This incident highlights the importance of proper restraints on these types of rides.

The seatbelts provided on the Thunder River Rapids rafts consisted of Velcro straps. It was vital that these were engaged correctly to provide the necessary restraint. Unfortunately, the Velcro was worn and this made correct engagement more difficult. It is thought that at least one of the four riders may have survived the incident if the rafts had a better quality seatbelt, such as a mechanical buckle type that are on aircraft. This is because as the raft was shaken by the mechanism the belt failed to hold and the rider dropped to the conveyor system below (Wolfe, 2018) (AAP, 2018).

### **Systems & Procedures**

Dreamworld has a series of operating procedures for the Thunder River Rapids ride however they were thought to be confusing (Sibson, 2018). During the investigation into the 2001 incident where empty rafts flipped, it was determined that the operator failed to follow the start-up and emergency procedures. The investigation also reviewed the operating procedures and

determined that the chance of a similar incident occurring with passengers on the rafts “is nil” (Wolfe, 2018). A senior engineer believed that the cause of the 2016 incident was the operator not following procedures and that if procedures were followed the “system is a safe system” (AAP, 2018) (Glover, 2018). There was also a lack of adequate emergency response procedures. Operators had discussed wanting better procedures and undertaking emergency drills, however, even two years after the incident, these have not been conducted at all (Jackson, 2018).

### **Assurance**

Over the history of the ride there had been several third-party reviews, inspections or audits carried out. Three years prior to the incident a safety audit was conducted, and it recommended replacing the complicated emergency shut down process with a single emergency stop button, but this recommendation was never actioned (AAP vid 12, 2018).

There was also a legal requirement for the rides to have a “certificate to operate” and the Thunder River Rapids ride certificate was due to expire in January 2016. The company sought an extension as they were unable to find a “competent person” as defined under the legislation to inspect the ride (Sibson, 2018). Eight days before the incident the ride was inspected by a third-party engineer. He declared the ride as “structurally sound and properly functioning” even though he did not complete the full safety audit and merely did a visual inspection. He also did not inspect the log book as was required by law in a push to have the ride certified before it expired, though he admitted that he could have refused to certify the ride because of a “lack of documentation” (Nothling, 2018) (Gribbin, 2018).

### **Human Factors**

The control panel for the ride was confusing (Sibson, 2018) and the operators needed to perform 36 different tasks in a one minute period, every minute (Sibson, 2018). This made for a system that encouraged human error, as it was not possible for the operators to be effective under these conditions. In addition to this, the engineering team believed the operators needed to simply follow procedures for the ride to be safe, not taking into account how difficult the procedures were or the actual workload. A senior engineer stated “In my view if procedures are followed the system is a safe system, you may as well not open the park. Procedures are there to be followed, if we don't follow procedures in everyday life, things happen.” This blind focus on procedures does not consider how the human interfaces with the machine and how the system advantages or disadvantages human performance.

### **Culture**

A maintenance worker stated that he believed that the “safety culture at Dreamworld is very sound” (Sibson, 2018) however this is in contrast to other workers who testified that familiarity had bred contempt with respect to the Thunder River Rapids ride (Sibson, 2018), where new attractions were given more focus than existing ones (Jackson, 2018). Junior operators believed there was a culture of fear and had engaged with their union over their working conditions and the demands put on them regarding lack of rest breaks (AAP vid 9, 2018).

The culture also appeared to not learn from incidents, with the 2001 incident of flipping rafts said to be a one off and having “nil” chance of occurring with riders on board (Wolfe, 2018). Even though the consequence appeared to be understood at the time with an engineer writing in an email “I shudder when I think if there had been guests on the ride.” (Sibson, 2018)

The park relied on its apparent good safety history rather than challenging how and when an incident could occur (AAP vid 1, 2018). They did not have an effective incident tracking system to help with the learning process. They introduced a database but there was “general reluctance to use what was a fairly complex database” by the operators (AAP vid 16, 2018).

Safety did not appear to be a value in the company culture. The former safety manager stated that “everyone thought it was someone else’s responsibility”. He believed that deficiencies in the corporate structure led to a lot of problems. In 2018 his corporate safety role was made redundant.

Around five months prior to the incident, a memo was issued to staff to ‘remain vigilant when monitoring conveyor movements’ for items that might interfere with the rafts. This suggests there was some understanding of hazards and consequences, but it does not appear to have driven any improvement activities or modifications to prevent an incident (AAP vid 20, 2018).

### **Ramifications**

The full ramifications of this incident are not yet clear. The Queensland government has initiated some legislative improvements to manage theme parks, but there is likely to be more recommendations coming from the Coronial Inquest when it releases its findings. Aside from the tragic loss of four lives, from the Dreamworld perspective, their guest numbers have remained low since the incident occurred, and it is struggling to attract patrons. This has led to their parent company suffering financial losses for the past two years and 50% decreases in the share price over the two year period (AFR, 2019).

The incident also provided an interesting lesson in crisis management. The company was scheduled to hold their annual general meeting in the days following the incident. The meeting went ahead and in it the CEO was awarded a performance bonus of \$840,000 including both shares and a cash component despite the four deaths days before (Doherty, 2016). From a public relations perspective this was not a successful event. The CEO also stated they had been in contact with the victim’s families, but this was publicly disputed by the families (Daniels, 2016). This further damaged the company reputation at a difficult time.

This incident will not only have ramifications for the families of the deceased, but for the survivors and the staff who responded due to the nature of injuries sustained by the victims. Four former staff members are suing Dreamworld for psychological damage (Wolfe, 2018).

These ramifications show how a process safety type incident can have significant impact on a business and its ability to continue operations in a positive way.

### Could the Principles of Process Safety Have Helped?

As had been shown, there were clear and systematic failures across the whole organization that led to this tragedy. Starting with knowledge and competence, which relates to organizational capability, had the operators been trained better in the safe operation of the ride as well as in emergency response, their performance that day may have been improved. From an engineering and design perspective, the design and installation of the ride was inadequate, it underwent undocumented changes which introduced hazards, and it was not adequately maintained. The systems and procedures for the operation and maintenance the ride was confusing and did not appear to contain necessary information. The assurance processes conducted did not seem to be thorough, rather they focused on keeping the ride operating and recommendations were not actioned. The ride was not designed with human factors in mind, from the high workload to the confusing operating panel. The organization culture did not seem to place a value on safety, it only focused on cost reduction. It also did not appear to be a learning culture, where lessons from the past are understood and embedded. Lastly at the time of crisis, the overall leadership displayed by the parent company was publicly found to be lacking.

There are transferrable learnings for the process industries from this incident, with some clear questions to ask. How are you managing your competency program to ensure you have the right capability? Are your designs adequate, maintained and any changes managed? Are your procedures thorough, identifying hazards, consequences and controls and easy to comprehend? How are you monitoring the operation of your facility? Does the design and operation of your facility enhance human performance or make it more difficult? Does your culture support safe operations?

### Conclusion

A focus on the elements of process safety can help identify what is important in a business. In this instance there had been recommendations for a low-cost instrumented safety system to be installed that would have prevented the incident from occurring. The importance of this was not understood by the organization, and the opportunity to upgrade the ride during its recent refurbishment was ignored. It is clear that the hazard and potential consequences and controls were not understood. As is often the case, when the hazard is not understood and therefore not managed, people suffer tragic consequences.

### References

- Kerin, T. 2017, *Managing Process Safety*. In the Core Body of Knowledge for Generalist OHS Professionals. Safety Institute of Australia, Tullamarine, VIC.
- ISC (IChemE Safety Centre). 2014, Safety Centre Framework, Available at <https://www.icheme.org/knowledge/safety-centre/framework/>, Accessed on January 2, 2019
- Sibson, E. 2018, Dreamworld deaths could have been prevented by press of a button: inquest, ABC News, Available at <https://www.abc.net.au/news/2018-06-18/dreamworld-fatal-accident-ride-had-broken-down-inquest-told/9871898>, Accessed on January 2, 2019
- Ludlow, M. Marin-Guzman, D. 2016, Dreamworld's rapids ride different from others around the world. Australian Financial Review, Available at <https://www.afr.com/news/dreamworlds-rapids-ride-different-from-others-around-the-world-20161101-gsfd07>, Accessed on January 2, 2019
- AAP, 2018, Dreamworld ride changes 'never approved', 9News, Available at <https://www.9news.com.au/2018/11/20/03/32/dreamworld-ride-passed-wphs-safety-audit>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 1, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 5, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 8, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 9, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 10, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 11, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019

- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 12, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 16, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Major changes mooted for theme park safety, 9 News, Video 20, Available at <https://www.9news.com.au/2018/12/06/03/33/dreamworld-inquest-enters-final-days>, Accessed on January 2, 2019
- AAP, 2018, Dreamworld inquest: Electrical engineering supervisor thought ride was safe, 9News, Available at <https://www.9news.com.au/2018/10/16/14/43/dreamworld-inquest-thunder-river-rapids-ride-engineers-give-evidence>, Accessed on January 2, 2019
- AFR, 2019, AAD share price, Australian Financial Review, Available at <https://www.afr.com/research-tools/AAD/share-prices?days=1095>, Accessed on November 26, 2018
- Doherty, B. 2016, Deborah Thomas set to receive \$840,000 in bonuses despite Dreamworld deaths, The Guardian, Available at <https://www.theguardian.com/australia-news/2016/oct/27/deborah-thomas-set-to-receive-840000-in-bonuses-despite-dreamworld-deaths>, Accessed on December 19, 2018
- Daniel, S. MacMillan, J. 2016, Dreamworld under fire for failing to contact victims' families directly, CEO to donate bonus, ABC News, Available at <https://www.abc.net.au/news/2016-10-27/dreamworlds-shareholders-ask-parent-company-to-support-victims/7970104>, Accessed on January 2, 2019
- Glover, M. 2018, Dreamworld inquest day 8: Electrical engineer back on the witness stand, 9News, Available at <https://www.9news.com.au/2018/10/17/10/49/dreamworld-inquest-engineer-to-appear-again>, Accessed on January 2, 2019
- Gribbin, C. 2018 Dreamworld supervisor bring families to tears after offering sympathies during inquest, ABC News, Available at <https://www.abc.net.au/news/2018-10-17/dreamworld-supervisor-sympathy-has-families-in-tears-inquest/10387186>, Accessed on January 2, 2019
- Huxley, J. 2018 Dreamworld inquest hears there was a 'total failure of everybody' to ensure ride's safety, ABC News, Available at <https://www.abc.net.au/news/2018-10-08/dreamworld-inquest-hears-total-failure-to-ensure-safety/10350034>, Accessed on January 2, 2019
- Intamin Worldwide, 2018, Infinity Falls – SeaWorld, Orlando, USA, Available at <https://www.intaminworldwide.com/infinity-falls-orlando/>, Accessed on December 12, 2018
- Jackson, E. 2018, Dreamworld prioritised new attractions over maintenance of old rides: inquest, Australian Financial Review, Available at <https://www.afr.com/real-estate/commercial/hotels-and-leisure/dreamworld-prioritised-new-attractions-over-maintenance-of-old-rides-inquest-20180626-h11urb>, Accessed on January 2, 2019
- Jackson, E. 2018, Inquest: Emergency stop button not regularly checked, Sunshine Coast Daily, Available at <https://www.sunshinecoastdaily.com.au/news/dreamworld-thunder-river-rapids-button-wasnt-regul/3543997/>, Accessed on January 2, 2019
- Jackson, E. 2018, Dreamworld ride trainer promoted after tragedy, staff wanted emergency training, Australian Financial Review, Available at <https://www.afr.com/news/dreamworld-ride-trainer-promoted-after-tragedy-staff-wanted-emergency-training-20180628-h11yke>, Accessed on January 2, 2019
- Nothling, L. Huxley, J. Gribbin, C. 2018, Dreamworld Thunder River Rapids ride triple-0 call revealed to inquest, ABC news, Available at <https://www.abc.net.au/news/2018-10-09/dreamworld-ride-declared-safe-days-before-tragedy/10352164>, Accessed on January 2, 2019
- Sibson, E. 2018, Dreamworld operator trained the morning four people were killed on rapids ride, ABC News, Available at <https://www.abc.net.au/news/2018-06-19/dreamworld-operator-on-first-day-when-four-people-died-on-ride/9885214>, Accessed on January 2, 2019
- Sibson, E. 2018, Dreamworld senior ride trainer promoted since preventable fatal tragedy, ABC News, Available at <https://www.abc.net.au/news/2018-06-27/dreamworld-trainer-promoted-since-four-killed-on-ride/9914188>, Accessed on January 2, 2019
- Sibson, E. 2018, Dreamworld ride operator instructed by senior park manager not to talk to police after tragedy, ABC News, Available at <https://www.abc.net.au/news/2018-06-20/dreamworld-operator-impossible-load-responsibilities-manage-ride/9889776>, Accessed on January 2, 2019
- Sibson, E. 2018, Dreamworld cut back maintenance months before fatal accident, inquest told, ABC News, Available at <https://www.abc.net.au/news/2018-06-25/dreamworld-inquest-told-of-ride-maintenance-cutbacks/9906214>, Accessed on January 2, 2019
- Sibson, E. 2018, Dreamworld ride operator 'highly distressed' giving evidence at inquest, ABC News, Available at <https://www.abc.net.au/news/2018-06-21/dreamworld-ride-operator-highly-distressed-give-evidence-inquest/9893308>, Accessed on January 2, 2019

Sibson, E. 2018, Dreamworld trainer told police that junior operator knew about emergency shutdown, inquest hears, ABC News, Available at <https://www.abc.net.au/news/2018-06-26/dreamworld-ride-operator-says-conveyor-was-never-stopped/9910192>, Accessed on January 2, 2019

The Sun, 2017, Girl, 11, dies after falling into the water on Splash Canyon ride during school trip to UK theme park, news.com.au, Available at <https://www.news.com.au/travel/travel-updates/incidents/girl-11-dies-after-falling-into-the-water-on-splash-canyon-ride-during-school-trip-to-uk-theme-park/news-story/f83330b0ce12ea11df2d089ece676519>, Accessed on January 2, 2019

Wolfe, N. 2018, Dreamworld first responders to sue theme park for 'psychological damage', news.com.au, Available at <https://www.news.com.au/lifestyle/real-life/news-life/dreamworld-first-responders-to-sue-theme-park-for-psychological-damage/news-story/e8fd7399eec9d165c657dbdb3ac35968>, Accessed on January 2, 2019

Wolfe, N. 2018, Coroner James McDougall requests proof all Dreamworld rides were certified. news.com.au, Available at <https://www.news.com.au/national/queensland/courts-law/coroner-james-mcdougall-requests-proof-all-dreamworld-rides-were-certified/news-story/e77275b97b0bbe9c1c541bda6df0035>, Accessed on January 2, 2019

Wolfe, N. 2018, Dreamworld engineer tells families: 'I apologise for not being to make eye contact with you', news.com.au, Available at <https://www.news.com.au/national/queensland/courts-law/dreamworld-engineer-tells-families-i-apologise-for-not-being-to-make-eye-contact-with-you/news-story/40545dc747c95eb96b0293c888d77d96>, Accessed on January 2, 2019

Wolfe, N. 2018, Safety report shows simple change on Dreamworld ride could have saved lives, news.com.au, Available at <https://www.news.com.au/national/queensland/courts-law/safety-report-shows-simple-change-on-dreamworld-ride-could-have-saved-lives/news-story/9c1fa2c195efd12f86a3e8ad516ea1b8>, Accessed on January 2, 2019